

HIMACHAL PRADESH
JAL SHAKTI VIBHAG

NOTICE INVITING TENDER

Sealed item rate tender on form PWD-6 and PWD-8 are invited by the Assistant Engineer, Jal Shakti Sub Division, Sihunta for the following work from approved and eligible contractors in Jal Shakti Vibhag so as to reach in this office on or before **25-10-2023** upto 12:00 PM and will be opened on the same day at 03:30 PM in the presence of intending contractors or their authorized representatives. The tender forms can be had from his office against cash payment (non-refundable) upto 12:00 PM on **25-10-2023**.

The earnest money in the shape of National Saving Certificate/Time Deposit Accounts/Saving Account in any of the post office or nationalized bank in Himachal Pradesh duly pledged in favour of Assistant Engineer, Jal Shakti Sub Division, Sihunta must accompany with each tender. Conditional tender and the tender received without earnest money will summarily be rejected. The offer of the tender shall be kept open for 120 days. Assistant Engineer, Jal Shakti Sub Division, Sihunta reserve the right to reject the tender without assigning any reasons. However such tender form duly filled should be accompanied by demand draft of cost of tender form drawn in favour of Assistant Engineer, Jal Shakti Sub Division, Sihunta.

Sr. No.	Name of Work	Estimated Cost (in Rs.)	Earnest money (in Rs.)	Cost of tender form (in Rs.)	Time limit
1	Restoration of rain damages of WSS Dhullara Sihunta in Tehsil Sihunta Distt. Chamba HP (SH: Fencing work around the RCC storage tank and filter bed at Chalara top point and P/F steel gate etc.)	143806	2876	250	2 Months
2	Providing WSS for PC Hab Dharamnalla Motla thakoli Dhullara Kasba and Sihunta Khas in Tehsil Sihunta (SH:- Excavation L/J and testing of GI pipe 65 mm dia at Rd 2470 to 3125 Sihunta line under JJM)	132882	2658	250	2 Months
3	Restoration of rain damages of FIS Upper Samote in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 3550 to 5660 = 2100)	145971	2919	250	2 Months
4	Restoration of rain damages of FIS Lower Samote in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 0 to 1750 = 1750)	162190	3244	250	2 Months
5	Retrofitting to CV Gola Kholan & Bhioura in Tehsil sihunta (SH:- Excavation L/J and testing of GI pipe 20 mm dia at Rd 5500/0 to 1350 = 1350 Rmt. To hab Bhiora under JSV Section Hatli)	117864	2357	250	2 Months
6	Providing WSS for PC Hab Dharamnalla Motla thakoli Dhullara Kasba and Sihunta Khas in Tehsil Sihunta (SH:- Excavation L/J and testing of GI pipe 50 mm dia at Rd 5690 to 6540) Source Salotu Sihunta Khas Under JJM)	130900	2618	250	2 Months
7	Providing WSS for PC Hab Dharamnalla Motla Thakoli Dhullara Kasba and Sihunta Khas in Tehsil Sihunta (SH:- Excavation L/J and testing of GI pipe 50 mm dia at Rd 4540 to 5690) Source salotu Sihunta Khas Under JJM)	164335	3287	250	2 Months


8	Restoration of rain damages of WSS Jassure Dukhar in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: C/O R/wall for protection of natural source at Sani for Rd 0 to 10 = 10 Rmt Ht. = 3 mtrs.)	198203	3964	250	2 Months
9	Restoration of rain damages to FIS Rajain Saroga in Tehsil Sihunta Distt. Chamba HP (SH:- C/O R/wall at Rd 1907 to 1917.50 = 10.50 mtrs.)	168468	3369	250	2 Months
10	Restoration of rain damages to FIS Lower Samote in Tehsil Sihunta Distt. Chamba HP (SH:- C/O P.C.C R/wall to Protect the main channel at Rd 1164 to 1170 = 7 Rmt. Ht. = 2.50 mtrs) (Roshan Lal house at Tikkri)	110959	2219	250	2 Months
11	Restoration of rain damages to FIS Upper Samote in Tehsil Sihunta Distt. Chamba HP (SH:- C/O P.C.C R/wall to Protect the main channel at Rd 1285 to 1293 = 8 Rmt. Ht. = 2.50 mtrs) (Puran Goswami house at Tikkri)	126551	2531	250	2 Months
12	Restoration of rain damages to FIS Khaggal Sihunta in Tehsil Sihunta Distt. Chamba HP (SH:- C/O P.C.C R/wall to Protect the main channel at Rd 5523.80 to 5527.30 = 3.50Rmt.	179665	3593	250	2 Months
13	Improvement of WSS Jassure Dukhar in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH:-Providing fencing pannel around the filter bed near sugad source.)	155701	3114	250	2 Months
14	Restoration of rain damages to FIS Lower Samote in Tehsil Sihunta Distt. Chamba HP (SH:- C/O PCC pucca main channel at Rd 2870 to 2895 = 25 Rmt.)	193341	3867	250	2 Months
15	Restoration of rain damages to WSS Rajain Saroga in Tehsil Sihunta Distt. Chamba HP (SH:C/O R/wall to protect the source & P/L and testing of GI pipe 50 mm dia from RD 770 to 960 = 190 Rmt. And Relaying and jointing of GI pipe 50mm dia at Rd 1170 to 1338 = 168 Rmt.)	190431	3709	250	2 Months
16	Restoration of rain damages for FIS Kuthera in Tehsil Sihunta Distt. Chamba HP (SH:- Removal of silt/slips from RD 0 to 840 = 840 Rmt. & Welding of leakage points Rd 840 to 1086 = 246 Rmt. = 41 Points.)	166711	3334	250	2 Months
17	Restoration of rain damages to WSS Narwadi Kamloon in Tehsil Sihunta Distt. Chamba HP (SH: Dismantalling relaying and jointing of Gi pipe 50mm dia at Rd 0 to 120, 1320 to 1410, 1560 to 1650, 2130 to 2230, 3770 to 3850, 5950 to 6020 Total = 550 Rmt.)	115249	2305	250	2 Months
18	Restoration of rain damages to FIS Khaggal Sihunta in Tehsil Sihunta Distt. Chamba HP (SH:- C/O P.C.C R/wall to Protect the main channel at Rd 5529.70 to 5532.20 = 2.50 Rmt.	128342	2567	250	2 Months
19	Restoration of rain damages to FIS Rajain Saroga in Tehsil Sihunta Distt. Chamba HP (SH:- C/O R/wall at	193655	3873	250	2 Months

	Rd 1795 to 1809 = 14 Rmt & C/O pucca main channel at Rd 1770 to 1800 = 30 Rmt..)				
20	Restoration of rain damages to FIS Khaggal Sihunta in Tehsil Sihunta Distt. Chamba HP (SH:- C/O R/wall to Protect the main channel at Rd 5527.30 to 5529.70 = 2.40 Rmt.	123203	2564	250	2 Months
21	Improvement of WSS Jassure Dukhar in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH:-C/O R/wall to protect the filter bed near sugad source of length = 8.50 Rmt. Height = 2.70 mtrs)	145046	2901	250	2 Months
22	Restoration of rain damages for WSS Dhullara Sihunta in Tehsil Sihunta Distt. Chamba HP (SH:-C/O RCC intake chamber at source P/L and jointing GI pipe 40 mm dia various Rds P/L RCC flat slab on storage tank at Kuthara point from Rd 880)	123106	2462	250	2 Months
23	Restoration of rain damages to FIS Lower Samote in Tehsil Sihunta Distt. Chamba HP (SH:- C/O RCC pucca main channel at Rd 2745 to 2770 = 25 Rmt.)	193341	3867	250	2 Months
24	Providing WSS for PC Hab Dharamnalla Motla Thakoli Dhullara Kasba and Sihunta Khas in Tehsil Sihunta (SH:- Exacavation L/J and testing of GI pipe 65 mm dia at Rd 3125 to 3780 Sihunta line under JJM)	160151	3203	250	2 Months
25	Providing WSS for PC Hab Dharamnalla Motla Thakoli Dhullara Kasba and Sihunta Khas in Tehsil Sihunta (SH:- Exacavation L/J and testing of GI pipe 50 mm dia at Rd 6540 to 7390) Source Salotu Sihunta Khas JJM)	130900	2618	250	2 Months
26	Restoration of rain damages for WSS Balli Bag Draman in Tehsil Sihunta Distt. Chamba HP (SH:- Dismantalling relaying and jointing of GI pipe 32mm dia from RD 310 to 570 = 260 Rmt. Rd 1275 to 1385 = 110 Rmt, Rd 1420 to 1495 = 75 Rmt & Rd 1665 to 1755 = 90 rmt (Total= 535 Rmt.)	129269	2585	250	2 Months
27	Restoration of rain damages for WSS Keod dharoon in Tehsil Sihunta Distt. Chamba HP (SH:-P/F barbed wire fencing around the intake chamber & C/O crate work to protect the intake chamber at Bhagood Nalla)	186083	3722	250	2 Months
28	Restoration of rain damages for WSS RikhGalla in Tehsil Sihunta Distt. Chamba HP (SH:-Dismantalling relaying and jointing of GI pipe 50mm dia from RD 9140 to 9314 = 174 Rmt, Rd 9515 to 9605 = 90 Rmt Rd 9730 to 9845 = 115 Rmt, & Rd 12145 to 12240 = 95 rmt, Rd 12775 to 12895 = 120 Rmt, (total = 594 Rmt.)	151844	3037	250	2 Months
29	Restoration of rain damages of FIS Lower Samote in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 3550 to 5350 = 1800 Rmt)	125118	2502	250	2 Months

30	Restoration of rain damages of FIS Upper Samote in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 0 to 1750 = 1750 Rmt)	162190	3244	250	2 Months
31	Restoration of rain damages of FIS Lower Samote in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 1750 to 3550 = 1800 Rmt)	166824	3336	250	2 Months
32	Restoration of rain damages of FIS Bhujjal Trimble in GP Samote. in Tehsil Sihunta Distt. Chamba HP (SH: Removal of silt from Rd 600 to 1800 = 1740 Rmt)	197200	3944	250	2 Months

TERMS AND CONDITIONS :-

1. The contractors/firms should be registered in Jal Shakti Vibhag in appropriate class.
2. The contractors/firms should have Income Tax/GST registration certificate.
3. The earnest money in the shape of National Saving Certificate/Time Deposit Accounts/Saving Account in any of the post office or nationalized bank in Himachal Pradesh duly pledged in favour of Assistant Engineer, Jal Shakti Sub Division, Sihunta with application form before the purchasing the tender documents.
4. The contractors/firms are required to quote their rates clearly both in words as well as in figures, failing which the Assistant Engineer reserve the right to accept/reject any or all tenders.
5. In case of sudden holiday on the date of opening of the tenders, the same will be opened on the next working day at the same time.
6. The conditional/ambiguous/telegraphic tenders or tender by fax or tender without earnest money will not be entertained/considered in any case.
7. The tender of those contractors/firms shall not be considered whose performance is not found good/satisfactory in the past


Assistant Engineer,
Jal Shakti Sub Division,
Sihunta Distt. Chamba


No. JSV-SHN-E-Tender/2023-

1498-1540

Dt. Sihunta the:- 12.10.2023

Copy forwarded to the following for information and necessary action please.

1. The Engineer-in-Chief, Jal Shakti Vibhag, Shimla.
2. The Chief Engineer, (DZ) Jal Shakti Department, Dharamshala.
3. The Superintending Engineer/Executive Engineer in Himachal Pradesh Jal Shakti Vibhag.
4. The Assistant Engineer Sub Division Banikhet/Chowari.
5. Notice Board
6. All the contractors/firms.


Assistant Engineer,
Jal Shakti Sub Division,
Sihunta Distt. Chamba